

NELSON HEAT TRACING SYSTEMS

PLT-CMD CONTINUITY MONITOR DEVICE


INSTALLATION INSTRUCTIONS

DESCRIPTION

The PLT-CMD continuity monitor device is used to monitor bus continuity on a parallel type heater cable. After the heater cable is installed on the pipe, connect the PLT-CMD to the opposite end of the power connection kit.

KIT CONTENTS

1 CMD Device	1 Power Termination
1 Conduit Locknut	1 Box Adapter
1 Sealing Grommet	1 Gasket
1 Stand-off	1 Tube of Silicone
1 Label	2 Pipe Clamps
2 Wire Nuts	



Note: This detail shows Braided "CB" Products only. For Overjacket "J" or "JT" Products see diagram on sheet 8.




⚠ WARNING:

Article 427-22 of the National Electrical Code requires that all heaters shall have metal coverings and be provided with branch circuit ground-fault protection.

STAND-OFF POSITIONING

Section View A A

(recommend installing at the
4 or 8 o'clock positions.)



- 1 Mark pipe where stand-off will be mounted.
- 2 Push heater cable through bottom opening of stand-off.
- 3 Slide the sealing grommet over the heater cable and position inside stand-off opening:

for Braided "CB" Products:


See "Grommet Installation for Braided "CB" Products", sheet 3.

for Overjacket "J" or "JT" Products


Proceed with step 4 below.

- 4 Apply silicone around the heater cable on top of the sealing grommet and fill any voids in sealing grommet.
- 5 Slide the box adapter over the heater cable and tighten securely to stand-off.
- 6 Prepare heater cable for power termination:
for Braided "CB" Products, see sheet 3.
for Overjacket "J" or "JT" Products, see sheet 4.
- 7 Terminate heater cable, see sheet 7.

SEALING GROMMET INSTALLATION FOR BRAIDED "CB" PRODUCTS




- 1 Slide braid back, allowing at least 13mm (.5") of heater cable exposed.
- 2 Cut and remove 13mm (.5") of heater cable.




- 3 Slide braid back over heater cable and twist excess braid into a pigtail.
- 4 Slide the sealing grommet over the heater cable and position inside stand-off opening.
- 5 Continue with step 4 on sheet 2.


BRAIDED "CB" PRODUCTS



- 1 Secure cable braid with fiberglass tape.
- 2 Slide braid back 127mm (5") to create a bulge.
- 3 At the bulge, separate the braid to make an opening.




- 4 While bending the heater cable, work it through the braid opening.




- 5 Pull the braid tight.
- 6 Cut off excess braid.
- 7 Proceed to "LT, CLT & HLT Products", sheet 5

OVERJACKET "J" or "JT" PRODUCTS




⚠ WARNING:
DO NOT CUT BRAID


- 1 Lightly cut around cable overjacket 127mm (5") from the end. Bend cable to break the overjacket.
- 2 Lightly cut overjacket up the center between first cut mark and the cable end. Bend cable to break the overjacket.




- 3 Remove overjacket from heater cable.




- 4 Move braid back toward the overjacket, creating a bulge.



- 5 At the bulge, separate the braid to make an opening.



- 6 While bending the heater cable, work it through the braid opening.



- 7 Pull the braid tight.
- 8 Cut off excess braid.
- 9 Proceed to "LT, CLT & HLT Products", sheet 5.


NELSON HEAT TRACING SYSTEMS

PLT-CMD CONTINUITY MONITOR DEVICE


INSTALLATION INSTRUCTIONS

FOR ALL NELSON LT, CLT & HLT PRODUCTS


(See sheet 6 for an alternate stripping method for HLT products.)




- 1 Lightly cut around cable outer jacket 102mm (4") from the end. Bend cable to break outer jacket.
- 2 Lightly cut the outer jacket up the center between the first cut mark & the cable end. Bend cable to break outer jacket.




- 3 Remove the jacket from the heater cable.



- 4 Shave the core material from the outside of each bus wire.



- 5 Starting at the end, pull each bus wire away from the core material.
- 6 Remove exposed core material.




- 7 Cut 6mm (0.25") off the end of each bus wire.
- 8 Proceed to "Power Termination", sheet 7.


⚠ WARNING:

DO NOT CUT BUS WIRES


HLT PRODUCTS ALTERNATE STRIPPING METHOD




- 1 Lightly cut around cable outer jacket 102mm (4") from the end. Bend cable to break outer jacket.
- 2 Lightly cut the outer jacket up the center between the first cut mark & the cable end. Bend cable to break outer jacket.




- 3 Remove the jacket from the heater cable.




- 4 Make a cut inside each bus wire.



- 5 Starting at the end, in the same plane as the cable, pull each bus wire away from the core material.



- 6 Remove the exposed core material.




- 7 Remove the remaining core material off the outside of each bus wire.
- 8 Cut 6mm (0.25") off the end of each bus wire.
- 9 Proceed to "Power Termination", sheet 7.


POWER TERMINATION

⚠ WARNING:

Bus wires must not touch or cross while inserting into power termination.




- 1 Insert bus wires into power termination.
- 2 Squeeze power termination opening and fill with silicone.



- 3 Push power termination to overlap jacket.
- 4 The silicone will set up in about 30 minutes with a complete cure after 24 hours.
- 5 Proceed to "Electrical Connection", sheet 8.


CMD DEVICE CONNECTION




Note: This detail shows Overjacket "J" or "JT" Products only. For Braided "CB" Products see diagram on sheet 1.

- ❶ Place gasket onto the box adapter.
- ❷ Position the CMD device onto the box adapter and secure it with the conduit locknut.
- ❸ Connect heater bus wires together with the CMD lead wires using the wire nuts. *(See diagram above.)*
- ❹ Make sure all wires are placed inside the CMD device.
- ❺ Place the box cover and box cover gasket onto the CMD device.
- ❻ See sheet 9 for "CMD Cable Connections to CM-1 and CM-2/1".


CMD CABLE CONNECTIONS TO CM-1 & CM-2/1




**Short side branch
(under 254mm (10"))**



Long side branch





Long side branch



will not work

Branch / Tee Piping (single circuit, multiple cable segments)



will not work

- CM-1, CM-2/1
- Heater Connection Kit
- Pipe
- Heater Cable
- Field Wiring
- CMD

Grouped Segments (several separate cables through single monitor point)